

Internal Quality Assurance Cell (IQAC)



Date: 22-10-2021

INFRASTRUCTURE MAINTENANCE – WORK COMPLETION REPORT

Date of Inspection: 14-09-2021

Date of Report: 20-09-2021

R.No	Room No/ Location	Observation mode	Type of Problem (Repairable/Replaceable/New work)	Estimated Budget	Actual Cost	Remarks (Material taken from store or Purchased)
106	EF-04	Projector screen fix	Repairable			
107	F-42	Projector Screen	Replaceable	-	-	Adjusted with old screen
108	F-44	Projector screen remove	Replaceable	-	-	
109	F-42	System is not working	Repairable			
Pending works if any						
NIL						

K. Sanyal
22/10/21
Prepared by
(Concerned in-charge)

K. Venkatesh
22/10/21
Verified By
[Dean Infra]

B
Authorized by
[Principal]

Copy to

- Office of the Rector
- Office of the Executive Director
- Office of the Principal
- Dean Admin
- Dean IQAC

Internal Quality Assurance Cell (IQAC)



VIGNAN's
INSTITUTE OF INFORMATION TECHNOLOGY
(AUTONOMOUS)

Beside VSEZ, Chavda, Helipad Road, Gandhinagar, Vadodha-390 015.

Date: 22-10-2021

INFRASTRUCTURE MAINTENANCE – WORK COMPLETION REPORT

Date of Inspection: 18-09-2021

Date of Report: 24-09-2021

R. No	Room No/ Location	Observation mode	Type of Problem (Repairable/Replaceable/New work)	Estimated Budget	Actual Cost	Remarks (Material taken from store or Purchased)
52	E-54	Internal LAN Connections	New work	9500	14302	Purchased LAN cable and fixing accessories
Pending works if any						
51	E-53	Projector arrangement	New work	-	-	Adjusted with old Projector and installation work was pending.

K. S. G. Patil
22/10/21
Prepared by
(Concerned in-charge)

K. Venkatesh Desai
Verified By 22/10/21
[Dean Infra]

[Signature]
Authorized by
[Principal]

Copy to

- Office of the Rector
- Office of the Executive Director
- Office of the Principal
- Dean Admin
- Dean IQAC

TAX INVOICE

(ORIGINAL FOR RECIPIENT)

INDUSTRIAL ELECTRICALS # 28-10-28/1, CHITRALAYA ROAD SURYABAGH, VISAKHAPATNAM PH: 0891-6634699, 6837222, 6663355 GSTIN/UIN: 37APNPP7147P1ZU State Name : Andhra Pradesh, Code : 37 E-Mail : levizag2006@gmail.com	Invoice No.	Dated
	3535	6-Oct-2021
Buyer V.I.I.T DUWADA VISAKHAPATNAM DUWADA AAAAL0584H State Name : Andhra Pradesh, Code : 37	Delivery Note	Mode/Terms of Payment
		30 Days
	Supplier's Ref.	Other Reference(s)
	Buyer's Order No.	Dated
	Despatch Document No.	Delivery Note Date
	Despatched through	Destination
Terms of Delivery		

Sl No.	Description of Goods	HSN/SAC	GST Rate	Quantity	Rate	per	Disc. %	Amount
1	D-LINK CABLE CAT 6-305 MTR BUNDLE	85446020	18 %	1.00 COILS	6,350.00	COILS		6,350.00
2	CASING & CAPING 2"	39172990	18 %	30.000 NOS	145.00	NOS		4,350.00
3	RJ45 JACK	85369090	18 %	100.000 NOS	4.50	NOS		450.00
								11,150.00
						C GST@9%	9 %	1,003.50
						S GST@9%	9 %	1,003.50

*(for VIT, System cell Dept
purpose)
BTR as
6/10/21
K. S. G. M.
7/10/21*

*19/5/2021
M*

JJ

09/10/21

*K. S. G. M.
22/10/21*

II. PHYSICALLY VERIFIED BY

ENTERED IN
Stock Register

Name: M. S. L. Y. R. S. A.

Page No: 152

₹ 13,157.00

Amount Chargeable (in words)
INR Thirteen Thousand One Hundred Fifty Seven Only
Date With Sign: [Signature]

Dept. System cell
Date With Sign: [Signature]
Company's Bank Details

Bank Name : HDFC BANK
A/c No. : 12432560000826
Branch & IFS Code : DABAGARDENS & HDFC0003243

Company's PAN : APNPP7147P

for INDUSTRIAL ELECTRICALS

Declaration
We declare that this invoice shows the actual price of the goods described and that all particulars are true and correct.



SUBJECT TO VISAKHAPATNAM JURISDICTION
This is a Computer Generated Invoice

Internal Quality Assurance Cell (IQAC)



Date: 08-11-2021

INFRASTRUCTURE MAINTENANCE – WORK COMPLETION REPORT

Date of Inspection: 24-09-2021

Date of Report: 06-10-2021

R. No	Room No/ Location	Observation mode	Type of Problem (Repairable/Replaceable/New work)	Estimated Budget	Actual Cost	Remarks (Material taken from store or Purchased)
80	EE Exploration Lab	EE Exploration Lab system not working-6	Repairable	-	-	
Pending works if any						
79	A37 & A36 Sergybrin lab & Bill gates lab	32-system problem	Replaceable	90000	-	Purchase order raised and waiting for delivery of systems

K. S. G. Reddy
8/11/21

Prepared by
(Concerned in-charge)

K. Venkatesh Reddy
08/11/21
Verified By
[Dean Infra]

[Signature]
Authorized by
[Principal]

Copy to

- Office of the Rector
- Office of the Executive Director
- Office of the Principal
- Dean Admin
- Dean IQAC

Internal Quality Assurance Cell (IQAC)



VIGNAN's

INSTITUTE OF INFORMATION TECHNOLOGY
(AUTONOMOUS)

Bevda #52, Oowda, Yellandu Post, Gajuwaka, YSRAPRASTHAM - 530 043

Date: 22-11-2021

INFRASTRUCTURE MAINTENANCE – WORK COMPLETION REPORT

Date of Inspection: 07-10-2021

Date of Report: 20-10-2021

R. No	Room No/ Location	Observation mode	Type of Problem (Repairable/Replaceable/New work)	Estimated Budget	Actual Cost	Remarks (Material taken from store or Purchased)
99	A21	Mouse Required -1	Replaceable	-	-	Mouse is adjusted from old stock
100	A24	CPU Problem, not working properly	Repairable	-	-	
101	A34	Projector not working	Repairable	-	-	VGA splitter & cable was changed
102	A34	System not working	Repairable	-	-	
103	A34	Projector Screen -1	Repairable	-	-	Scrolling was adjusted
106	B11	Projector Screen, LCD PROJECTOR Alignment	Repairable	-	-	
107	B11	CPU Problem	Repairable	-	-	
109	B24	LCD PROJECTOR, System not working	Repairable	-	-	VGA splitter was changed
113	B22	LCD PROJECTOR Connector, Projector Screen	Repairable	-	-	
Pending works if any						
98	A11	CPU not working	Replaceable	-	-	CPU need to be replacement
104	Tutorial Room	Projector not working, & CPU not working	Replaceable	-	-	CPU need to be replacement
105	B14	Screen, CPU Problem	Replaceable	-	-	CPU need to be replacement
108	B13	Projector, CPU not working	Replaceable	-	-	CPU need to be replacement

R. No	Room No/ Location	Observation mode	Type of Problem (Repairable/Replaceable/New work)	Estimated Budget	Actual Cost	Remarks (Material taken from store or Purchased)
110	B22	CPU not working, and projector Screen fixing	Replaceable	-	-	CPU need to be replacement
111	B23	LCD PROJECTOR, CPU not working	Replaceable	-	-	CPU need to be replacement
112	B22	CPU not working	Replaceable	-	-	CPU need to be replacement
114	B34	LCD PROJECTOR & CPU not working	Replaceable	-	-	CPU need to be replacement
115	B46	CPU not working	Replaceable	-	-	CPU need to be replacement

K. Sanyal
22/11/21
Prepared by
(Concerned in-charge)

K. Venkatesh
Verified By
[Dean Infra] 22/11/21

[Signature]
Authorized by
[Principal]

Copy to

- Office of the Rector
- Office of the Executive Director
- Office of the Principal
- Dean Admin
- Dean IQAC